


NOZZLE CHECK PATTERN

Continuous lines = nozzles firing. Gaps or missing lines = clogged nozzle.

C #00AEEF



M #EC008C



Y #FFF200



K #000000

